


Montageanleitung Sockel 0346, 100 mm hoch
Mounting Instructions for 100 mm High Base Type 0346
Instructions de Montage pour Socle Type 0346, Hauteur 100 mm

hawa 



DETAIL A


nachdem das Gewinde geformt ist
after the thread is formed
après que le fil soit formé

4Nm




DETAIL B

11 Nm



DETAIL C

11 Nm



hawa 

hawa GmbH

D 88489 Wain

Industriestraße 12
Tel. +49 7353 98460
Fax +49 7353 1050
info@haewa.de

F 67600 Sélestat

hawa France Sarl
22 Rue Roswag
Tel. +33 6 72713309
info@haewa.fr

USA Duluth, GA 30097

haewa Corporation
3768 Peachtree Crest Drive
Tel. +1 770 9213272
Fax +1 770 9212896
info@haewa.com