


Montageanleitung Sockel 0346, 100 mm hoch

Mounting Instructions for 100 mm High Base Type 0346

Instructions de Montage pour Socle Type 0346, Hauteur 100 mm


**DETAIL A**

nachdem das Gewinde geformt ist
after the thread is formed
après que le fil soit formé


4Nm

**DETAIL B**

11 Nm

**DETAIL C**

11 Nm



Änderungen vorbehalten/Specifications subject to modifications/Sous réserve de modifications

© häwa, 07/2025

0346-0001-00-77

D 88489 Wain

häwa GmbH
Industriestraße 12
Tel. +49 7353 98460
info@haewa.de

F 67600 Sélestat

häwa France Sarl
22, Rue Roswag
Tel. +33 672 71 3309
info@haewa.fr

USA Duluth, GA 30097

haewa Corporation
3768 Peachtree Crest Drive
Tel. +1 770 9213272
info@haewa.com
