


Montageanleitung Sockel 0346, 100 mm hoch  
Mounting Instructions for 100 mm High Base Type 0346  
Instructions de Montage pour Socle Type 0346, Hauteur 100 mm

hawa 



#### DETAIL A


nachdem das Gewinde geformt ist  
after the thread is formed  
après que le fil soit formé

4Nm




#### DETAIL B

11 Nm



#### DETAIL C

11 Nm





**hawa GmbH**

**D 88489 Wain**

Industriestraße 12  
Tel. +49 7353 98460  
Fax +49 7353 1050  
info@haewa.de

**F 67140 Eichhoffen**

hawa France Sarl  
8 B Rue des Industries  
Tel. +33 3 88088880  
Fax: +33 3 88088859  
info@haewa.fr

**USA Duluth, GA 30097**

haewa Corporation  
3768 Peachtree Crest Drive  
Tel. +1 770 9213272  
Fax +1 770 9212896  
info@haewa.com